

Joint spi adaptable 150x180x14.5/16

Référence : P1BEP000264

Détails

Joint spi adaptable pour tracteurs Case-
Ih/Claas/Renault/Fendt/Ford/John Deere/Massey Ferguson/Mc
Cormick/New Holland/Steyr
Diamètre Intérieur : 150mm
Diamètre Extérieur : 180mm
Epaisseur : 14,5/16mm
Référence Origine : 0.900.0091.1, 000051785, 0000809316,
03493560, 047702, 053850, 053850R1, 069104, 06914440,
1-33-742-086, 1000087865, 1000089537, 11988156, 12018035,
1255600, 133742086, 14605013, 15196337, 1589869, 1966832C1,
218352, 219001342, 2201872, 2326003940, 24001899121, 2410055,
247546A1, 2C.047702, 2C.133267, 31795910, 3493560, 3665712M1,
3785511M1, 3907166, 3907166M1, 401693401700, 4213267M1,
4235529M1, 452140A1, 47702, 499940, 51785, 53850, 53850R1,
57013480, 5H.7380606901, 6000104965, 6000105276, 6000147702,
6005009891, 6005011172, 6005030587, 6005105276, 602325,
604014, 609024656, 610047702, 6193408M1, 6193704M1, 6914440,
7000056, 7001275, 73404064, 738.06.069.01, 7380606901, 74540,
81881800, 85821288, 85825035, 87313744, 87349641, 87415728,
87611436, 881012890, 90000911, 91474161, 93-1454, 931454,
947147, 974147, 98655.4, 986554, A047702, A133267, A47702,
ACP0321910, ACP321910, AL159594, C149702, CAR47702,
D10110560, EPJ1402, ER047702, ER133267, ER148307, ER149702,
ER149703, ER47702, F339300020020, H524.300.020.100,
H524300020100, H524300020170, IFI04103, JXAL159594, KH4967,
KH4967*, L500641, L500786, LL7160601, M97414.7, M974147,
M986554, NFHPR047702, PP9161033, RE195990, RE204870,
RE238999, RE248610, RFHPR047702, S0640272, S774377,
T748935, T774377, U20230496, V31795910, V34051910, V602895,
V81881800, VA044702, VA047702, VA133267, VA149702, VA47702,
VKH4967



Un joint spi ou joint d'étanchéité à lèvres à ressort est un type de joint d'étanchéité mécanique utilisé pour empêcher les fuites de fluides ou de poussières à travers l'interface entre deux pièces en mouvement relatif, généralement un arbre rotatif et un boîtier fixe. Référence Origine : 0.900.0091.1, 000051785, 0000809316, 03493560, 047702, 053850, 053850R1, 069104, 06914440, 1-33-742-086, 1000087865, 1000089537, 11988156, 12018035, 1255600, 133742086, 14605013, 15196337, 1589869, 1966832C1, 218352, 219001342, 2201872, 2326003940, 24001899121, 2410055, 247546A1, 2C.047702, 2C.133267, 31795910, 3493560, 3665712M1, 3785511M1, 3907166, 3907166M1, 401693401700, 4213267M1, 4235529M1, 452140A1, 47702, 499940, 51785, 53850, 53850R1, 57013480, 5H.7380606901, 6000104965, 6000105276, 6000147702, 6005009891, 6005011172, 6005030587, 6005105276, 602325, 604014, 609024656, 610047702, 6193408M1, 6193704M1, 6914440, 7000056, 7001275, 73404064, 738.06.069.01, 7380606901, 74540, 81881800, 85821288, 85825035, 87313744, 87349641, 87415728, 87611436, 881012890, 90000911, 91474161, 93-1454, 931454, 947147, 974147, 98655.4, 986554, A047702, A133267, A47702, ACP0321910, ACP321910, AL159594, C149702, CAR47702, D10110560, EPJ1402, ER047702, ER133267, ER148307, ER149702, ER149703, ER47702, F339300020020, H524.300.020.100, H524300020100, H524300020170, IFI04103, JXAL159594, KH4967, KH4967*, L500641, L500786, LL7160601, M97414.7, M974147, M986554, NFHPR047702, PP9161033, RE195990, RE204870, RE238999, RE248610, RFHPR047702, S0640272, S774377, T748935, T774377, U20230496, V31795910, V34051910, V602895, V81881800, VA044702, VA047702, VA133267,

Caractéristiques	
Types de produits	Carter du moyeu